

JUL-19-2001 11:13

ADAMS CASSAN MACLEAN

1 613 828-0024

P.13/21

WO 01/39353


097889642

PCT/CA99/01100


FIG. 1

1/6


STD




UT



LT



CT



UMB







WO 01/39353

09/889642

PCT/CA99/01100

FIG. 2

2/6

**Dual Tandem
UT + CT + UMB****Dual Tandem
UT + LT****Triple Tandem
UT + CT + CT + UMB****Triple Tandem
UT + CT + LT**

WO 01/39353

09/889642


PCT/CA99/01100

FIG. 3


3/6




UMH with Center Tandem Motor
 $UMH + CT = UT$




=



UMH with Lower Tandem Motor
 $UMH + LT = STD$



=



JUL-19-2001 11:13

ADAMS CASSAN MACLEAN

1 613 828 0024

P.16/21


WO 01/39353

09/889642

PCT/CA99/01100

FIG. 4

4/6



JUL-19-2001 11:13

ADAMS CASSAN MACLEAN

1 613 828 0024 P.17/21


09/889642

WO 01/39353

PCT/CA99/01100

FIG. 5

5/6



JUL-19-2001 11:13

ADAMS CASSAN MACLEAN

1 613 828 0024 P.18/21

WO 01/39353

09/889642

PCT/CA99/01100

6/6

FIG. 6

